


## Sendai Nuclear Power Station Unit 2: Plant status as of 10.00am, October 25 (Daily report)

Operations	
Results (10:00, Oct 24 – 10:00, Oct 25)	<p>[Electric power] <b>50% output is maintained</b> as of 10.00am, Oct 25</p> <p>[Main process]</p> <ul style="list-style-type: none"> <li>➤ The primary system (reactor system) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ The secondary system (turbine and generator system) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> </ul> <p>[Tests and inspections]</p> <ul style="list-style-type: none"> <li>➤ Operator's self-inspection (periodical equipment inspection items) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ Regulatory inspection <ul style="list-style-type: none"> <li>• Inspection associated with the reactor startup ongoing (started on Oct 8)</li> </ul> </li> </ul>
Plans (10:00, Oct 25 – Oct 26)	<p>[Main process]</p> <ul style="list-style-type: none"> <li>➤ The primary system (reactor system) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ The secondary system (turbine and generator system) <ul style="list-style-type: none"> <li>• Oct 26 Load up from 50% to 75% as electric power</li> </ul> </li> </ul> <p>[Tests and inspections]</p> <ul style="list-style-type: none"> <li>➤ Operator's self-inspection (periodical equipment inspection items) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ Regulatory inspection <ul style="list-style-type: none"> <li>• Inspection associated with the reactor startup</li> </ul> </li> </ul>

# Sendai Unit 2: Restart operation process

Oct 25, 2015



Translated by JANSI: For the original text, please go to: [http://www.kyuden.co.jp/var/rev0/0048/9906/news\\_2\\_151025.pdf](http://www.kyuden.co.jp/var/rev0/0048/9906/news_2_151025.pdf)