


## Sendai Nuclear Power Station Unit 2: Plant status as of 10.00am, October 28 (Daily report)

	Operations
Results (10:00, Oct 27 – 10:00, Oct 28)	<p>[Electric power] <b>Load up from 75% to 95% is in progress</b> as of 10.00am, Oct 28</p> <p>[Main process]</p> <ul style="list-style-type: none"> <li>➤ The primary system (reactor system) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ The secondary system (turbine and generator system) <ul style="list-style-type: none"> <li>• Oct 28 Load up is ongoing from 75% to 95% as electric power</li> </ul> </li> </ul> <p>[Tests and inspections]</p> <ul style="list-style-type: none"> <li>➤ Operator's self-inspection (periodical equipment inspection items) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ Regulatory inspection <ul style="list-style-type: none"> <li>• Inspection associated with the reactor startup ongoing (started on Oct 8)</li> </ul> </li> </ul>
Plans (10:00, Oct 28 – Oct 29)	<p>[Main process]</p> <ul style="list-style-type: none"> <li>➤ The primary system (reactor system) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ The secondary system (turbine and generator system) <ul style="list-style-type: none"> <li>• Oct 28 95% output will be achieved</li> </ul> </li> </ul> <p>[Tests and inspections]</p> <ul style="list-style-type: none"> <li>➤ Operator's self-inspection (periodical equipment inspection items) <ul style="list-style-type: none"> <li>• None</li> </ul> </li> <li>➤ Regulatory inspection <ul style="list-style-type: none"> <li>• Inspection associated with the reactor startup</li> </ul> </li> </ul>

# Sendai Unit 2: Restart operation process

Oct 28, 2015



Translated by JANSI: For the original text, please go to: [http://www.kyuden.co.jp/var/rev0/0049/0221/news\\_2\\_151028.pdf](http://www.kyuden.co.jp/var/rev0/0049/0221/news_2_151028.pdf)